Please amend the first full paragraph of page 21 by changing "168" to -160—in line 6, as follows:

The upper end of the packer cup assembly 150 connects with a cementing manifold 160 through which a cement slurry and drilling fluids may be selectively introduced into the casing 112. A cement port connection 162 provides access into the manifold 168-160 for a cement slurry introduced through a supply line 163. The upper end of the manifold 160 is connected to a top drive adapter or hook adapter 170 through which drilling fluids may be pumped through the combination tool 101 into the casing 112.